

Holte Shock Sync and Adapter Subs

Holte Mfg. Co
25310 Jeans Road
Veneta, Or 97487
T. 541-935-5054
F. 541-935-5430
www.drilling.com

MADE IN USA

HOLTE MANUFACTURING

11.2 PIN X 9.4 SHOCK SYNC SUB
EXPLODED VIEW AND PARTS

HOLTE MANUFACTURING



ADAPTER PART NUMBERS

#	Description (qty)	Qty	PN	Spares
1	O-Ring 441-7 x 7.5 x .250	2	960000-0441	4
2	O-Ring 371-8.500 x 8.875x .1875	1	960000-0371	2
3	11.2 x 9.4 Shock Sync Sub Hex Seal	2	510211-0001	4
4	O-Ring 383-14.000 x 14.375 x .1875	1	960000-0383	2
5	11.2 x 9.4 Shock Sync Sub	1	510211-101410	0
N/A	9.4" Hex Joint Connector Bolt Assembly		090209-400030	2
6	9.4 RC Retaining Bolt	2	090209-0004	2
7	208 O-Ring 5/8" X 7/8" X 1/8"	2	960000-0208	2
8	9.4 RC Delrin Washer	4	090209-0009	2
9	O-Ring 212-.875 x 1.125 x .125	2	960000-0212	2
10	9.4 Ret Nut	2	900078-0002	2

**Spares are recommended part quantities to have on-hand for service*

†The Bolt-washer-O-ring–O-ring-Nut can also be purchased as an assembly (2 needed; 090209-400030) which contains all the subsequent parts needed (items 4-8).

The two O-rings that make up Part 1 fit inside the diameter into 2 O-Ring grooves. Parts 2 and 3 fit around the smaller, top, diameter. Part 4 fits around the larger diameter in the middle of the part.

Holte Mfg. Co. (541)935-5054 f. (541)935-5430
www.drilling.com Sales@drilling.com

9.4 PIN X 11.2 BOX ADAPTER
EXPLODED VIEW AND PARTS

HOLTE MANUFACTURING



ADAPTER PART NUMBERS

#	Description (qty)	Qty	PN	Spares
1	O-Ring 365-7 x 7.375 x .1875	1	960000-0365	1
2	O-R ing381-12 x 12.375 x .1875	1	960000-0381	1
3	9.4 Pin 11.2 Box	1	090211-0002	
N/A	11.2" Hex Joint Connector Bolt Assembly		090211-0001	2
4	11.2_Bolt_O-Ring_Large	2	960000-0218	2
5	11.2_Bolt_O-Ring_Small	2	960000-0214	2
6	11.2 Delron Washer	2	090211-0004	2
7	11.2 Ret Pin Bolt	2	090211-0020	2
8	11.2 Ret Nut 1.250-7	2	090211-400007	2

**Spares are recommended part quantities to have on-hand for service*

†The Bolt-washer-O-ring–O-ring-Nut combo, can also be purchased as an assembly (2 needed; 090211-0001) which contains all the subsequent parts needed (items 4-8).

SHOCK SYNC EXPLODED VIEW AND PARTS LIST



SHOCK SYNC PART NUMBERS

#	Description (qty)	Qty	PN	Spares
1	O-Ring 371-8.500 x 8.875x .1875	1	960000-0371	1
2	O-Ring 383-14.000 x 14.375 x .1875	1	960000-0383	1
3	11.2 Pin x Box RC Hex Shock Sync	1	090211-0013	0
N/A	11.2" Hex Joint Connector Bolt Assembly		090211-0001	2
7	11.2 Ret Pin Bolt	2	090211-0020	2
6	11.2 Delron Washer	2	090211-0004	2
5	11.2_Bolt_O-Ring_Small	2	960000-0214	2
4	11.2_Bolt_O-Ring_Large	2	960000-0218	2
8	11.2 Ret Nut 1.250-7	2	090211-400007	2

**Spares are recommended part quantities to have on-hand for service*

†The Bolt-washer-O-ring–O-ring-Nut combo, can also be purchased as an assembly (2 needed; 090211-0001) which contains all the subsequent parts (items 4-8).

HOLTEMANUFACTURING
WWW.DRILLING.COM